ILLEGIB Approved For Release 2001/03/03 : CIA-RDP78T05439A000500020061-1

Approved For Release 2001/03/03 : CIA-RDP78T05439A000500020061-1

DECLASS REVIEW by NIMA/DOD

TCS #2639/65 PID/ABCB 89/65 23 April 1965 Copy #____

25X1A

MENORAHIUM FOR: Chief, Nuclear Energy Division, OSI

ATTENTION:

, snb/ned/osi

THROUGH:

Chief, Requirements Branch, Reconnaissance

Group, CGS

FROM:

Chief, Photographic Intelligence Division, CIA

SUBJECT:

Measurement of Ice-Free Areas at the Tomsk

Atomic Energy Complex, USSR

REFERENCES:

Requirement No. C-SI5-82,167

CIA Project No. 30209-5

1. Areas of melted ice on the Tom River resulting from discharge points at the Tomak AE Complex were measured by the MPIC Technical Intelligence Division as follows:

25X1D

The above tabulation is a total acreage figure for each mission, and includes separate ice-free areas and the intervening refrozen areas.

25X1D 25X1D 25X1D 2. Preliminary measurements by the photo analyst (PID/ABCB Memo 45/05, dated 23 Feb 65) compared favorably, especially the total ice-free areas. The WPIC/TID measurements of the ice-free areas ranged between 7 to 5% lower except for which were about 15% lower. The frozen areas on also compared well; larger differences on the other missions are in part due to the difficulty in interpreting the

5-16973

25X1D 25X1D 25X1D	boundary of a refrozen channel. As a result the photogrammetrist measured a narrower section on that . A larger frozen area was included on that used by the photo analyst.
	3. EPIC/TID measurements were also obtained for the pre- cooler section, the holding area prior to discharge into the Tom River. These measurements are considered approximate due to the vapor clouds that partially cover the area. The measure- ments as received are as follows:
	Area
25X1D	Trench Canal Reservoir Lake Stream Outlet
	HOTE: All measurements given are in acres. * Considered unreliable by photo analyst.
25X1D	The best clear coverage of the above was on acreage of the reservoir lake for this mission is about 20% lower than the preliminary measurement made by the project analyst.
	4. All measurements in this final memorandum have been made by the NFIC Technical Intelligence Division, and are considered accurate within + 5% for the Tom River ice-free section and + 10% for the Tom River refrozen section. No accuracy statement was given for the pre-cooler section due to the partial cloud cover.
25X1A	5. The photo analyst on this project was who may be contacted on extension 2317 should you have further questions.

6. This memorandum and the previous partial response as referenced completes the project.